

9/24/84

PRELIM DRAFT SITE INSP REPORT

PAGECOMMENTS

FIGURE 6

- did not photocopy very good, well locations are difficult to read.

3-7

- Of known the following information would be helpful concerning the scope of the ct. DEP's removal action?

- was soil clean below 25 feet?

- How much soil was removed and over what area?

4-2

- In the second part of section 4-1, is each paragraph a summary of the report referenced at the start of the paragraph, or are results listed in each paragraph part of a non specific data summary?

- ✓ - bis(2-ethylhexyl) phthalate was found in the field blank at 8 PPB, please mention or subtract from 25 PPB reported in the Hinman well.

- ✓ - only one on-site well contained 20 PPB of bis(2-ethylhexyl) phthalate, the other well had contamination below that reported for the field blank.

- ✓ - methylene chloride was detected below field blank in one on-site well (2 vs. 4 PPB), and just above in another well, please mention.

- ✓ - note high levels of chlorinated hydrocarbons in ERT-5 well.

NOT  
CHANGED  
in final  
di-n-butyl phthalate found at 5 PPB in ERT-1 well  
not 25 PPB, please reference source of results.



PAGE

COMMENT

4-2

- reference source of 22 ppb fluoranthene in  
on-site ERT well.

correct

Appendix D

✓ - assume concentrations on metals are ppm from  
reference on page 4-3. please state units.

correct